


Plug for E-2 Trail Header Transport

# GC40


# 2-21-2013

## WIRING HARNESS (GC40)



- #1 - Running Lights
- #2 - L Turn
- #3 - Strobe Master
- #4 - S Strobe Slave
- #5 - RT Turn
- #6 - Strobe Slave (? pin Deutsch plug)


- Wire codes
- White (10ga) ground
  - Blue (10ga) brake signal
  - Black (10ga) constant power
  - Green (14ga) running lights
  - Red (14ga) L Turn
  - Brown (14ga) RT Turn
  - Yellow (14ga) Strobe Slaves
  - Orange (14ga) Strobe on



# GC48

2-21-2013


## WIRING HARNESS (GC48)



- #1 = Running Lights (2 pin plug)
- #2 = LT Turn (3 pin plug)
- #3 = Strobe Master (3 pin plug)
- #4 = Strobe Slave (3 pin plug)
- #5 = RT Turn (3 pin plug)
- #6 = Strobe Slave (2 pin Deutsch plug)

### Wire codes

- White (10ga) ground
- Blue (10ga) brake signal
- Black (10ga) constant power
- Green (14ga) running lights
- Red (14ga) LT turn
- Brown (14ga) RT turn
- Yellow (14ga) strobe slaves
- Orange (14ga) strobe on



14 feet

Orange and Blue harness separate from main harness